

# NEWS from CPSC

## U.S. Consumer Product Safety Commission

Office of Information and Public Affairs

Washington, DC 20207

FOR IMMEDIATE RELEASE

July 1, 1997

Release # 97-149

CONTACT: Ken Giles

(301) 504-7052

## CPSC, Shimano Announce Recall of Bicycle Components

WASHINGTON, D.C. - In cooperation with the U.S. Consumer Product Safety Commission (CPSC), Shimano American Corp. of Irvine, Calif., is voluntarily recalling more than 1 million cranks installed on bicycles in North America. The crank is used to connect the pedal to the frame of the bike. If the crank breaks, the rider's leg can be injured by contact with the broken crank or the rider can lose control of the bike, fall and be injured.

Shimano has received more than 630 reports of cranks breaking in North America resulting in 22 injuries, including cuts and fractures.


The cranks have been installed on more than 200 models of bicycles manufactured since 1994 and sold under at least 49 brand names. Most bicycle manufacturers have sold bicycles that are involved in this recall. The cranks also may have been installed as an upgrade as part of the Altus, Acera and Alivio groups of components. The cranks are numbered FC-CT90, FC-M290 and FC-MC12. These numbers are located on the back or inner side of the right crank arm.

Consumers should check their bicycles' crank assemblies. If they are involved in this recall, consumers should stop using their bicycles immediately and call Shimano at 800-353-4719 to arrange for the free replacement and installation of a new crank assembly at a nearby authorized repair shop. Consumers can also arrange for the free replacement with their bicycle dealers.

List of 49 bicycle brands that may have installed Shimano cranks:

Alpinestar	Iron Horse	Norco	Specialized
Balance	Jamis	Novara	Schwinn
Bianchi	Kona	Oryx	Scott
Caloi	L.L. Bean	Parkpre	Signature
Cannondale	Marin	Pavan	Softride
Cycle Pro	Maxam	Performance	Terry Precision
Diamondback	Mikado	Peugeot	Timberline
Dirt Research	Mongoose	Proflex	Trek
Fisher	Mtn. Tek	Raleigh	Univega
Fuji	Motiv	Research Dynamics	Victoria Precision
GT	Murray	Roadmaster	
Giant	Nashbar	Ross	
Huffy	Nishiki	Royce Union	

Other brands also may have installed Shimano cranks. Consumers should check their bicycles.



FC-CT90  
FC-M290  
FC-MC12

IF THESE NUMBERS APPEAR  
ON THE BACK OR INNER  
SIDE OF THE RIGHT CRANK,  
PLEASE CALL SHIMANO OR  
SEE YOUR BICYCLE DEALER  
FOR REPLACEMENT.

[Send the link for this page to a friend!](#) The U.S. Consumer Product Safety Commission is charged with protecting the public from unreasonable risks of serious injury or death from more than 15,000 types of consumer products under the agency's jurisdiction. Deaths, injuries and property damage from consumer product incidents cost the nation more than \$700 billion annually. The CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical, or mechanical hazard or can injure children. The CPSC's work to ensure the safety of consumer products - such as toys, cribs, power tools, cigarette lighters, and household chemicals - contributed significantly to the 30 percent decline in the rate of deaths and injuries associated with consumer products over the past 30 years.

To report a dangerous product or a product-related injury, call CPSC's hotline at (800) 638-2772 or CPSC's teletypewriter at (800) 638-8270, or visit CPSC's web site at [www.cpsc.gov/talk.html](http://www.cpsc.gov/talk.html). To join a CPSC email subscription list, please go to [www.cpsc.gov/cpsclist.aspx](http://www.cpsc.gov/cpsclist.aspx). Consumers can obtain this release and recall information at CPSC's Web site at [www.cpsc.gov](http://www.cpsc.gov).