

# IMPORTANT RECALL NOTICE

## Carbon Forks On Certain 2011 Model Year Specialized Bicycles:

2011 Sirrus Comp	2011 Vita Comp	2011 Tricross
2011 Sirrus Expert	2011 Vita Expert	2011 Tricross Comp
2011 Sirrus Elite	2011 Vita Elite	2011 Tricross Sport

The brake boss housed in the Advanced Group carbon fork on the specified Specialized bicycles can disengage from the fork and allow the brake assembly to contact the wheel spokes while rotating, posing a fall hazard.

Sold from June 2010 to August 2011.

### Remedy:

Stop riding affected bicycles immediately and return your bicycle to an Authorized Specialized Retailer for a free replacement fork.

If you have any questions contact Specialized at:

**(877) 808-8154**

or visit their web site at:

[www.specialized.com](http://www.specialized.com)